EXHIBIT T

WORK ORDER # 00-0000061

Close Date: 01/07/2000 W.O. #: 00-0000061

OPS 53 DFS PAS KURZ METER FIT-430 MALFUNCTION

Task #:	01W	Wo Type:	CM	Reason For Outage:	ERR
Originator:	FOUNR	Priority:	1.00	Expense Class:	B242-G30
Phone:		Ext.:		Est. Duration:	
Down Time:	0.00	Assigned By:	JENSK	Actual Duration:	
Emp. Hours:	1.00	Assigned To:	ME	Response Days:	3
Vendor Hours:	0.00	Total Labor Hrs:	1.00	Response Hrs:	0
Request Date:	01/05/2000	Request Time:		Response Mins:	0
Sched Start Date:		Sched Finish Date:		Perf By Warranty:	N
Completion Date:	01/07/2000	Completion Time:	08:11:45		
Delay Description:					

COMPLETE 1/7/00 MJ

Equipment #: 24-FIT-430 Down Time:

Description : KURZ FLOW METER FLUE GAS MASS FLOW
Comments: BOP MATRIX 13400 REQUIRED

INVESTIGATE CAUSE OF MALFUNCTION AND LATCHING FSL FSLL ALARM RESULTING IN BURNER FAILURE

-MALFUNCTION CAUSE BY MOISTURE ON PRODES. MALFUNCTION CLEARED AFTER FLOW DRIED PRODES

Close Date: 01/28/2000 W.O. #: 00-0002795

MONTHLY PM FURNACE FLOW METER KURZ

Task #:	ICPM11.01M	Wo Type:	PM	Reason For Outage:	
Originator:		Priority:	3.00	Expense Class:	B242-053
Phone:		Ext.:		Est. Duration:	
Down Time:	0.00	Assigned By:	CLARM	Actual Duration:	0.00
Emp. Hours:	2.00	Assigned To:		Response Days:	
Vendor Hours:	0.00	Total Labor Hrs:	2.00	Response Hrs:	
Request Date:		Request Time:		Response Mins:	
Sched Start Date:	02/05/2000	Sched Finish Date:	02/05/2000	Perf By Warranty:	N
Completion Date:	01/28/2000	Completion Time:	11:40:42		
Delay Description:					

Equipment #: 24-FIT-430 Down Time:

Description : KURZ FLOW METER FLUE GAS MASS FLOW
Comments: PM PASSED

CSGPO-453 | 0085 Pg.5

RDER No: 00-0000061 Page 1 01/05/2000 10:48:31 AM

Task #: 01W (CM)
OPS 53 DFS PAS KURZ METER FIT-430 MALFUNCTION

ense Class:	B242-G30	By Warranty:	N	Priority:	1.00
quested on:	01/05/2000	at:			
Scheduled Start:		Finish:			
Completion Date:		Time:			
Originator:	FOUNR	Reason for Outage:			
Phone:		Ext:			
Assigned To:	T	By:	JENSK		

Craft	# People	# Hours
MI	2	12.00

Eq #: 24-FIT-430
KURZ FLOW METER FLUE GAS MASS FLOW
Serial #:
Cost Center:
Gen Ledger #: DFSPAS
Department: Building: DFS/PAS
Floor/Room: 3-4 / PAS
Location: TE-6-D-506 DFS/PAS

System: DFS
Subsystem: DFSPAS

Must Be Down: N
Est Down Time:
Down Time:

Meter #	Reading

Safety Notes:

Comments: BOP MATRIX 13400 REQUIRED

INVESTIGATE CAUSE OF MALFUNCTION AND LATCHING FSL FSLL ALARM RESULTING IN BURNER FALURE

List extra parts used and comments here
Malfunction cause by moisture on probes. Malfunction cleared after flow dried probes.

Employee Code	for Equipment #	Date	Name	Reg Hrs	Ot Hrs
		5 JAN 00	P. Timmons	1 Hr	

Task Instructions

>BOP<

Employee P. Timmons Lead/Supervisor [illegible]

Conditional release _____ Full release [illegible]

Operations acceptance [illegible] Date 06/JAN/00

WAS CALIBRATED M&TE USED DURING THE WORK PERFORMED? YES ____ NO N/A
IF "YES" RECORD M&TE USED BELOW.